

CASPIR Aircraft Accident Cards

Serial: 3621

Title: Fleet Fort serial:3621 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-April-25. Fleet Fort II s/n 3621. This accident involved 2 people. Simpson KR, Husband DG

Keywords: RCAF Fleet Fort II, 3621, 3 WS, 3 Wireless School, Pacific Junction Manitoba, 1943-April-25, Husband, Simpson RCAF L20

Created: 1943-04-25

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000741#3621>

DUTY ON WHICH ENGAGED:
Wireless exercise.

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

D-14.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

Engine began running rough after
take off and pilot found he could
not make base safely so forced landed

COMPOSITION:

EC/AV/1/9/10/11/12

2 mi. south of wireless school. Engine
stopped before he completed landing
and A/C nosed up when it struck new-
ly plowed strip. RECOMMENDATIONS:

PRIMARY CAUSE:

~~54. Engine failure in the air.~~

~~Piston seized and partly broke up.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

17. Forced Landing
(17)

NIL

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~33. Technical defect.~~

26. Engine trouble
Accident
(26)

RECORDED BY

DATE

CHECKED BY

DATE