

CASPIR Aircraft Accident Cards

Serial: BM702

Title: Airspeed Oxford Mk. II serial:BM702 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-April-29. Oxford II s/n BM702. This accident involved 2 people. Finlay EV, Raymond JA

Keywords: RAFOxford II,BM702,35 SFTS,35 Service Flying Training School,Aerodrome,1943-April-29,Finlay,RaymondRCAF L20

Created: 1943-04-29

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#BM702>

DUTY ON WHICH ENGAGED:

Flying training.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

A/C had almost reach take off speed when a loud report, presumed to be the sound of a tyre bursting was heard. The A/C lurched and swung violently to left, the port u/C collapsed, and severe damage was caused to the A/C.

DATE:

COMPOSITION:

000/0713/USM

RECOMMENDATIONS:

PRIMARY CAUSE:

15. Tire failure.

2. Steering

(12)

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

NIL

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

38. Ground loop

37. Tire Burst

(37)

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____