

UTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
Sequences 10,13,15,17,22.	OR COMMANDING OFFICER'S REPORT:
•	D-14 #54.
ATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:
After landing A/C began to swin	
off runway. Pilot opened throt	
ittempted to take off at too lo	
speed. Wing dropped and A/C gr	
looped.	RECOMMENDATIONS:
DIMARY CAUCE	
PRIMARY CAUSE:	
Swinging.	
12. SNUNG	
12	ACTION TAKEN:
	(A) DISCIPLINARY (5) TECHNICAL (C) OTHER
	(A) Personally admonished by Squadron Commander.
SECONDARY CAUSE OR CONTRIBUTING FACTORS	
Sl. Swinging on landing.	Management of the Control of the Con
38. Ground loop.	RECORDED BY DATE
	CHECKED BY DATE