Ş	PILOT OTHERS		AIRFRAME			ENGIN		
YPE OF A	UNIT #1 S.F.T.S. Camp Borden	#1 TC		miles w	vest of New Lowel	DATE 9.5.4	3 TIME 1400	1, 100 1, 100 1, 1515 1, 1515
-	A/C TYPE Harvard 77.		No. 3045	C F C A	RASH AT. A	SE ME	DAY NIGHT	S HERT!
-	N A M E	RAI		DUTY	INJUR		SERIOUS	Det Det
-NE	Dewar, K.B.	J.i.	AC R12544	8 PP	DIED 16	isly Injur 3-5-43	FATAL INJURY	T Z XXER
ENGINE							CARD SERIAL No.	S S S S S S S S S S S S S S S S S S S
PE OF						y 13-000000.	×	
_	TYPE A/F & ENGINE No. OF	EXTENT F	REPORT SERIAL FORM No.	DATE	нои	RS FLOWN BY F		1 1 1/3/
		Totally			INST. NIGHT	ON TYPE	AL SOLO 6 MOS.	
GORY	Wasp 213795/115	24 Seri	ously		28 14	52 58 S	94 91 85	T C C C C C C C C C C C C C C C C C C C
	SIGNAL NO. & DATE UN	IT No. & DAT	E COM.	No. & DAT	E REPORT	FILE	DATE	TO SAR AR

)
	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:)
	Air to Ground Camera Gun)
	NATURE OF ACCIDENT AND STAGE OF FLIGHT: A/c engaged on air to ground firing	DATE: COMPOSITION:)
	seen to pull up & then start a	· · · · · · · · · · · · · · · · · · ·	,
	shallow dive until it hit ground.		,
	Witnesses state that a loud crack)
	was heard and black smoke was seen to come from A/C .	That, as a breach of instructions regarding safety)
	o como 11 om 11/ os	officer at the Bombing Target were improperly carr-	
	PRIMARY CAUSE:	ied out as per standing orders at No. 1 S.F.T.S.,	
	32. Pilot error.	disciplinary action should be taken against the)
	Appears to be a possibility that pilot was practicing forced land-	parties concerned.)
	ing, decided to go around again,	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER)
	pulled up and then lost control,	Conclusions of A.I.B.	,
	crashing to the ground. Possibility that pilot momentarily blacked	See accident summary No. 952.	,
	out.		,)
•)		,
) SECONDARY CAUSE OR CONTRIBUTING FACTORS:		
	1	RECORDED BY DATE)
•)		ł
	1	CHECKED BY DATE)
			·)