

CASPIR Aircraft Accident Cards

Serial: FE350

Title: North American Harvard Mk. IIB serial:FE350 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-May-12. Harvard IIB s/n FE350. This accident involved 1 person. Rigby K

Keywords: RAFHarvard IIB,FE350,41 SFTS,41 Service Flying Training School,Aerodrome,1943-May-12,RigbyRCAF L20

Created: 1943-05-12

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE350>

DUTY ON WHICH ENGAGED:

air to ground firing

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D.14 #63

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Ground looped on landing

DATE:

COMPOSITION:

see page 2 ✓

RECOMMENDATIONS:

PRIMARY CAUSE:

~~1. Ground loop~~

2. SWUNG.

2

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Pupil has ground looped previously, & is being tested by two examiners with a view to wastage.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~3. Cross winds & gusts~~

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____