

## CASPIR Aircraft Accident Cards

---

**Serial:** FE807

**Title:** North American Harvard Mk. IIB serial:FE807 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-May-13. Harvard IIB s/n FE807. This accident involved 2 people. Bennett HJ, Morris HJA

**Keywords:** RAFHarvard IIB,FE807,34 SFTS,34 Service Flying Training School,Aerodrome,1943-May-13,Bennett,MorrisRCAF L20

**Created:** 1943-05-13

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE807>



DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Night flying circuits and landings. OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

A/C stalled and dropped a wing before making contact with the ground.

COMPOSITION:

D-14 #60

RECOMMENDATIONS:

PRIMARY CAUSE:

~~39. Flattening out too soon.~~

HEAVY

4

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER  
Log book endorsed.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~38. Ground loop.~~

RECORDED BY

DATE

CHECKED BY

DATE