		FAIL				FAIL		Section of the
d CA	USES OF		CCIDENTS					7 21/2
Uplands, Ont. # 3	PLACE M.A.		•	H.O. FILE	-5 - 43 1300-	TIME 2310 -RW195		M WELL
A/C TYPE Harvard II	No. BW195		CRASH CAT. C l		ME	DAY	NIGHT	시아! / 💞
NAME RA	NK NO.	DUTY	INJUR	IES		SERI	ious	>
Ringer, J.A. L	AC R162179	PP	Nil			FATAL	INJURY	N U S
							1 1	
N 100 N S		-		:			RD AL Ng.	
T C C							X	
TYPE A/F NO EXTENT	REPORT SERIAL	DATE	нои	IRS FLOW	N BY PI	LOTS		1 - 1 / .0
& ENGINE NO. OF DAMAGE	FORM No.	DATE	INST. NIGHT	ON TYP	_	OTAL	LAST	T A LANG.
Harvard II BW195 Slight1	У			39 2		66		[] \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
Wasp 4976/Y178 N.L.			29 11	39 2	0 77	. 00		1 0 E 47 G
800				6/-		41		H O KY
SIGNAL NO. & DATE UNIT NO. & DA	TE COM.	No. & D.	ATE REPOR	т	FILE	T C	DATE	
ै A102 15-5-43								

NATURE OF ACCIDENT AND STAGE OF FLIGHT: Preceding A/C had knocked over and extinguished a red lantern marking turning point and A/C BW195 while taxing turned too soon and hit extinguisher which was placed well off tarmac and clear of taxi strip. PRIMARY CAUSE: 2. Hitting obstructions. OR COMMANDING OFFICER'S REPORT: DATE: COMPOSITION: PATE: COMPOSITION: Officer in charge has been warned that lights are to be immediately relit if knocked over or otherwise extinguished.	DUTY ON WHICH THOUSED	
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Preceding A/C had knocked over and extinguished a red lantern marking turning point and A/C BW195 while taxing turned too soon and hit extinguisher which was placed well off tarmac and clear of taxi strip. PRIMARY CAUSE: 2. Hitting obstructions. Date: COMPOSITION: PRIMARY CAUSE: DATE: COMPOSITION: PRIMARY CAUSE: DATE: COMPOSITION: COMPOSITION: PRIMARY CAUSE: COMPOSITION: COMPOSIT	Sequences 25 (6,7,8)	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT.
Preceding A/C had knocked over and extinguished a red lantern marking turning point and A/C BW195 while taxiing turned too soon and hit extinguisher which was placed well off tarmac and clear of taxi strip. PRIMARY CAUSE: 2. Hitting obstructions. DATE: COMPOSITION: COMPOSITION	1	
extinguished a red lantern marking turning point and A/C BW195 while taxiing turned too soon and hit extinguisher which was placed well off recommendations: tarmac and clear of taxi strip. Officer in charge has been warned that lights are to be immediately relit if knocked over or otherwise extinguished. PRIMARY CAUSE: 2. Hitting obstructions. 9. COALISTONS.		
turning point and A/C BW195 while taxiing turned too soon and hit extinguisher which was placed well off recommendations: tarmac and clear of taxi strip. Officer in charge has been warned that lights are to be immediately relit if knocked over or otherwise extinguished. PRIMARY CAUSE: 2. Hitting obstructions. 9. Coalismoss.		COMPOSITION:
taxiing turned too soon and hit extinguisher which was placed well off RECOMMENDATIONS: tarmac and clear of taxi strip. Officer in charge has been warned that lights are to be immediately relit if knocked over or otherwise extinguished. PRIMARY CAUSE: 2. Hitting obstructions. 9. Coalismoss.		
tinguisher which was placed well off tarmac and clear of taxi strip. Officer in charge has been warned that lights are to be immediately relit if knocked over or otherwise extinguished. 9. Collisions.		
be immediately relit if knocked over or otherwise extinguished. 9. Coalsons.	tinguisher which was placed well off	RECOMMENDATIONS:
extinguished. 9. Coalsons.	tarmac and clear of taxi strip.	Officer in charge has been warned that lights are to
9. COLLISIONS.	PRIMARY CAUSE.	
9. COLLISIONS.		extinguished.
	1 12/8/02.	
ACTION TAKEN: (A) Disciplinary (B) Technical (C) Other	\mathcal{J}	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
N;L.	<i>I</i>	N _i L _•
)	
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
RECORDED BY DATE		RECORDED BY DATE
CHECKED BY DATE	(Control of the Control of the Contr	CHECKED BY DATE