Ų	PILOT OTHERS		LURE	ENGINE ENGINE	S. A.S. S. T. C.
ıπ A		CAUSES OF	ACCIDENTS		
О	#13 D.F.1.D.	PLACE		DATE 19.5.43	
Υγ	St.Hubert #3 T	C M.A.			DAY NIGHT
ı	TYPE Harvard II	3101	CRASH CAT. B	X ME	DAY NIGHT S
_	NAME	RANK NO. DU	IV INJUI		
	Campbell, L.F.	LAC R170682 F	P Nil		FATAL INVUEN
fs1					m z
ENGINE					(M)
ENG					CARD C
H _O					
Ш С.					$\boldsymbol{U} \setminus \boldsymbol{U} \setminus \boldsymbol{U}$
۲	TYPE A/F NO. EXTENT		ATE HOL	JRS FLOWN BY PI	IOTS III
	OT BAMA	GE FORM NO.	INST. NIGHT		-/
_	Harvard 3101 Serio	usly	76 /	DUAL SOLO DUA	L SOLO 6 MOS.
GORY	masp acarry 17 17 Williams		16 4	21 15 64	
EGO					T - 1 - 1 - 1 - 1 - 1
CATE	SIGNAL NO. & DATE UNIT NO &	DATE COM, No. 8	DATE REPOR		T) 9

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
Navigation flight.	OR COMMANDING OFFICER'S REPORT:
_	D-14 #97
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:
Pilot landed and A/C began to swing	COMPOSITION:
to.left. He overcorrected with rudder and brake and A/C ground	
looped.	
toopeu.	RECOMMENDATIONS:
•	
PRIMARY CAUSE:	
32. Pilot error.	
	ACTION TAKEN:
	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER Personally admonished. Log book endorsed "Error of
	Judgment and pilot given extra fatigue duties.
	This pupil pilot will be progress checked.
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
38. Ground loop.	
61. Swinging on landing	RECORDED BY DATE
	CHECKED BY DATE