AIRFRAME FAILURE ENGINE FAILURE CAUSES OF ACCIDENTS UNIT #41 S.F.T.S. COM. PLACE Weyburn 2 M.A. DATE 21.5.43 TIM 1630 H Q.FILE 1100-38-44 A/C TYPE Harvard II NO. 3841 D CRASH CAL. C.1 SE ME DAY NIGHT TYPE TOMBLE TOMBLE SERIOUS Tomlinson, D. LAC 1208884 PP Nil FATAL INJURY OF	M - W - W - W - W - W - W - W - W - W -
VINIT #41 S.F.T.S. COM. PLACE DATE 21.5.43 TIM 1630	150
Harvard II 3041 CAT. C.1 X X O	1= /16b/
	いしき フランス
1 1 TAG 1 1 TAG 1	FIF 1/.6º/
Curtis, S.R. LAC 1681199 PP Nil	Z KHIR
CARD SERIAL NO.	O U S O U D
	S CHOING
TYPE A/F NO. EXTENT REPORT SERIAL DATE HOURS FLOWN BY PILOTS.	O LEND GE
Harvard 3841 Nil. INST. NIGHT DUAL SOLO DUAL SOLO DUAL SOLO FORS] - /&//
Wasp 9544/172 Slightly	m trigh
	421/28/2
SIGNAL NO & DATE UNIT NO & DATE COM. NO & DATE REPORT FILE DATE	

DUTY ON WHICH ENGAGED: FE337 - Air to ground firing.	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:	5 3 4 47 00
3041 - Precautionary landings.		D-14_#109
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:	
Two Harvard A,C were approaching to land on the same runway. FE337	COMPOSITION:	
completing its landing run, was	* * *	
struck by 3841, which was still		
airborne.	RECOMMENDATIONS:	
PRIMARY CAUSE:		
6		
-		
	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER	
	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER	
6 COLLISIONS		
v		
SECONDARY CAUSE OR CONTRIBUTING FACTORS:		
	RECORDED BY	DATE
	ALCONOLD BY	
	ONE OF THE OWNER OW	DATE
	CHECKED BY	DATE