. F	PILOT OTHERS		RAME	FAILUF		170 P			ALLURE	TO THE STATE OF TH
\ <u>\</u>		CAUSE	5 0	F AC	CIDEN					T VILLO
E E	St.Hubert #13 S.F.T.S.	,,	€ 4 mi le•	les SW	Chamb.	ly,	H.Q. FILE	5•43 1 1100-4		= Z NASTS.
	A/C FTEet Finch #	No.	4904	CR/ CAT		Ļ	X M	E D	X NIGHT	10101/37/
	NAME	RANK	No.	DUTY	1	NJUF	IIES		SERIOUS	-1-1 : 1 / 5 /
	Johnson, E.H.	PO J2	2322 7	FI	Nil			F	'ATAL INJURY	S A PL
FENGINE									CARD SERIAL NO.	S Undirit
TYPE OF		V.T.E. D.E.O.O.T.	leen l			HOU	JRS FLOWN	BY PILO	V ¥	Track!
		XTENT REPORT DAMAGE FORM	SERIAL No.	DATE	L.V.S.F.		ON TYPE		TAL LAST	
	Finch 4904 S1:	ight ly			INST.		DUAL SOLO			TAKE
GORY	Kinner 6467/1813 N	iL.			43	35		145	254	
E G							1		<u> </u>	
 	SIGNAL NO. & DATE UNI	T No. & DATE	сом.	No. & DATE		REPOR	T	FILE	DATE	

Ferrying A/C St. Hubert to St. Johns, P.Q.	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT: D-14 #34	
nature of accident and stage of flight: Engine spluttered and failed. Pilot carried out forced landing	DATE: COMPOSITION: 18/10/15/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1	
in field, rolled through ditch and overturned.		
1	RECOMMENDATIONS:	
PRIMARY CAUSE: 54. Engine failure in the air. An air lock might have formed in the fuel system, causing the engine failure. FORCE D ANDING.	ACTION TAKEN: (A) Disciplinary (B) Technical (C) Other This officer was given a severe personal admonition and also detailed for extra duties.	
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	,	
LINGINE TROUBLE -	RECORDED BY DATE	
ACCIDENT	CHECKED BY DATE	
, , , , , , , , , , , , , , , , , , ,)))))))))))))))))))	