

ACCIDENT CLASSIFICATION											
UNIT 41 S.F.T.S. Weyburn		COM. 2	PLACE Halbrite,, R.L.F.			DATE 11.6.43	TIME 2359				
A/C TYPE Harvard IIB			No. FE.300	CRASH CAT. C.1		S.E. X	M.E.	DAY	NIGHT X		
PERSONNEL			RANK	NUMBER	DUTY	INJURIES		SIGNAL			
Hemmings, A.F.			LAC	1537368	PP	Nil		No. A.84	DATE 12.6		
								D 14 (REVISED)			
								No. 7	CHECKED <input checked="" type="checkbox"/>		
								No.55			
ENGINE		ENGINE NUMBER(S)		HOURS FLOWN BY PILOTS							
ANI 14461/41-12906		-		ON TYPE				TOTAL			
				INST.	NIGHT	SOLO	DUAL	SOLO	DUAL		
				23	10	54	54	76	82		
ACCIDENT CLASSIFICATION											

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

4
2
1
7
4
2
1
FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STAT RV
FATAL
INJ
INJ 3RD
INJURY
M N

162
61
60
59
58
57
56
55
54
53
52
51
50
49
48
47
46
45
44
43
42
41
40
39
38
37
36
35
34
33
32
31

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
RAF
M N

PURPOSE OF FLIGHT:

Night flying circuits.

TECHNICAL OFFICER'S REPORT:

No technical defect.
Damaged tips of airscrew; port mainplane wrinkled
and burst tyre through A/C ground looping.

NATURE OF ACCIDENT:

Pilot coming in to land in light variable wind on runway experienced violent swing, was unable to correct.
Tyre burst causing damage to airscrew and mainplane.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

✓

CLASSIFICATION:

~~61. Swinging on landing.~~

2. *Swing.*

2

SECONDARY OR CONTRIBUTORY FACTORS:

~~43. Tyre trouble.~~

ACTION TAKEN:

NIL