

## CASPIR Aircraft Accident Cards

---

**Serial:** AH188

**Title:** North American Harvard Mk. II serial:AH188 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-June-18. Harvard II s/n AH188. This accident involved 1 person. Porich V

**Keywords:** RAFHarvard II,AH188,41 SFTS,41 Service Flying Training School,Aerodrome,1943-June-18,PorichRCAF L20

**Created:** 1943-06-18

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AH188>



) PURPOSE OF FLIGHT:  
) Exercises 8, 9, 13 and 15.

) TECHNICAL OFFICER'S REPORT:  
) No technical defect. Pupil selected u/c lever for  
) flap/<sup>lever</sup>causing stbd. u/c locking latch to disengage.

) NATURE OF ACCIDENT:  
) Pilot's report states that stbd. wheel  
) **collapsed** and horn started blowing as  
) he was taxiing slowly off runway. It  
) is almost certain on inspection that  
) he moved u/c lever instead of flap  
) lever and subsequently moved u/c lever  
) back to down position.

) COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:  
) FINDINGS:

) SUMMARY No.

) UW



) CLASSIFICATION:  
) 32. Pilot error.

) SECONDARY OR CONTRIBUTORY FACTORS:  
) 6. Undercarriage drill at end of  
) landing run.

) ACTION TAKEN:

) Log Book endorsed. 7 days C.C.