

CASPIR Aircraft Accident Cards

Serial: 11415

Title: Avro Anson Mk. II serial:11415 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-June-29. Anson II s/n 11415. This accident involved 3 people. McIntosh WA, Mcqueen DG, Ross GH This accident had 3 fatalities. Leading Aircraftman William Albert McIntosh RCAF Killed in Flying Accident service no:R/175129 Anson 11415, Pilot Officer George Hugh Ross RCAF Killed in Flying Accident service no:J/24463 Anson 11415, Leading Aircraftman Donald Gordon McQueen RCAF Killed in Flying Accident service no:R/165955 Anson 11415

Keywords: RCAFAnson II,11415,5 SFTS,5 Service Flying Training School,Glenmorris Ontario,1943-June-29,Mcintosh,Mcqueen,RossRCAF L20

Created: 1943-06-29

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#11415>

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

100/10-2-116

Seq. 19

NATURE OF ACCIDENT:

Fail plane appeared to fall from aircraft during flight.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No. 94

The aircraft structure failed due to stresses imposed in recovering from a high speed dive. The dive resulted from the student putting aircraft into an unusual position during instrument flying practice.

Command to be informed that instructor had done an excessive amount of flying while at this school (123:40 hours in 29 days)

CLASSIFICATION:

~~28. Structural failure.~~

OUT OF CONTROL

SECONDARY OR CONTRIBUTORY FACTORS:

STRUCTURAL FAILURE

ACTION TAKEN: