

CASPIR Aircraft Accident Cards

Serial: BW188

Title: North American Harvard Mk. II / 2A serial:BW188 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 2 aircraft on 1943-July-03. They are: Harvard II s/n AJ934, Harvard I s/n BW188. This accident involved 2 people. Hugo D, Murray VC

Keywords: RAFHarvard I,BW188,41 SFTS,41 Service Flying Training School,Aerodrome,1943-July-03,Hugo,MurrayRCAF L20

Created: 1943-07-03

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#BW188>

ACCIDENT CLASSIFICATION

UNIT 41 S.F.T.S. Weyburn	COM. 2	PLACE L.A.	DATE 3.7.43	TIME 0315
A/C TYPE Harvard II Harvard I		NO. AJ.934 BW.188	CRASH CAT. C.3 C.7	H.Q. FILE 1300-AJ.934
		S.E. X	M.E.	DAY NIGHT X

COMMAND

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
					NO.	DATE
Murray, V. C.	LAC	R174702	PP	Nil	A117	3.7
Hugo, D.	LAC	1605206	PP	Nil		
					D 14 (REVISED)	
					NO.	CHECKED
					3	X
					#10	

MONTH

ENGINE	ENGINE NUMBER(S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
Resp	8545/1104 Slightly						
Resp	12135/1864 Nil						
		20	5	16	36	76	77
		21	7	44	51	75	81

STAGE OF FLIGHT

7
4
2
1
7
4
2
1
FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ.
3RD
INJURY
5
RAF
M

ACCIDENT CLASSIFICATION

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30

TYPE OF UNIT
TYPE OF A/C
CATEGORY

61
60
59
58
57
56
55
54
53
52
51
50
49
48
47
46
45
44
43
42
41
40
39
38
37
36
35
34
33
32
31

PURPOSE OF FLIGHT:

) Night flying. Taxiing prior to take-off

TECHNICAL OFFICER'S REPORT:

No technical defect.

NATURE OF ACCIDENT:

) Pupil pilot of AJ934 taxiing on
) return runway at night failed to keep
) a proper look-out and overtook and
) collided with EW188.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

) ~~3. Hitting other aircraft.~~

) 4. *collisions*

9

SECONDARY OR CONTRIBUTORY FACTORS:

) ~~2. Carelessness.~~

ACTION TAKEN:

Pupil charged - admonished, log book endorsed
and grounded for one month.