

CASPIR Aircraft Accident Cards

Serial: FE285

Title: North American Harvard Mk. IIB serial:FE285 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-August-04. Harvard IIB s/n FE285. This accident involved 1 person. Ewell FO

Keywords: RAFHarvard IIB,FE285,34 SFTS,34 Service Flying Training School,Aerodrome,1943-August-04,EwellRCAF L20

Created: 1943-08-04

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE285>

ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.S. Medicine Hat		COM. 4	PLACE Main Aerodrome		DATE 4-8-43	TIME 1600		
A/C TYPE Harvard IIB		NO. FE285	CRASH CAT. D 1	S.E. X	M.E.	DAY X	NIGHT	
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL	
Ewell, F.O.		LAC	1461499	PP	Nil		NO. DATE	
<i>Accident</i>						D 14 (REVISED)		
						NO. 8/1	CHECKED <input checked="" type="checkbox"/>	
						21		
ENGINE	ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS					
Wasp	41-12433/13910 Nil		INST.	NIGHT	ON TYPE		TOTAL	
R1340-AN-1					SOLO	DUAL	SOLO	DUAL
					36	50	71	92

COMMAND
 MONTH
 STAGE OF FLIGHT
 FORCED LANDING
 TAXING
 LANDING
 TAKE-OFF
 FLIGHT
 STATRY
 FATAL
 INJ. 1st
 INJ. 2nd
 INJ. 3rd
 INJ. 4th
 INJ. 5th

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Local Solo Exercises

TECHNICAL OFFICER'S REPORT:

Tail wheel tube burst.

NATURE OF ACCIDENT:

Tail wheel tube burst on landing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

LUC/UTWF

CLASSIFICATION:

43. Tire trouble

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

N.A.