

CASPIR Aircraft Accident Cards

Serial: 2856

Title: North American Harvard Mk.II serial:2856 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-August-27. Harvard II s/n 2856. This accident involved 1 person. Sharman EV

Keywords: RAFHarvard II,2856,34 SFTS,34 Service Flying Training School,Aerodrome,1943-August-27,SharmanRCAF L20

Created: 1943-08-27

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2856>

ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.S. Medicine Hat COM. 4 PLACE M.A. DATE 27-8-43 TIME 1800
 H.Q. FILE 1100-28-56

A/C TYPE HARVARD II NO. 2856 CRASH CAT. "D"¹/₄ S.E. X M.E. DAY X NIGHT

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Sharman, E.V.	Lt	1268254	PP	Uninj.	NO.	DATE

~~XXXXXXXXXX~~

D 14 (REVISED)
 NO. 50 CHECKED

#133

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
Wasp S3H1	11548/A213819 Nil	-	-	4	11	38	52

ACCIDENT CLASSIFICATION

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

4
2
1
7
4
2
1
1
FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STAT'RY
FATAL
INJ. 3rd
INJURY 5th
RAT
M

PURPOSE OF FLIGHT:

Solo exercise.

TECHNICAL OFFICER'S REPORT:

Nil

NATURE OF ACCIDENT:

Struck fence bordering tarmac while taxiing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

TCO/PCT

CLASSIFICATION:

2. Hitting obstructions.

SECONDARY OR CONTRIBUTORY FACTORS:

32. Pilot error.

ACTION TAKEN:

Log book endorsed and extra duties.