

CASPIR Aircraft Accident Cards

Serial: 11274

Title: Avro Anson Mk. II serial:11274 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-August-14. Anson II s/n 11274. This accident involved 3 people. Wood CJ, Turkington RT, Tucker C

Keywords: RCAFAnson II,11274,19 SFTS,19 Service Flying Training School,Low Flying Area,1943-August-14,Tucker,Turkington,WoodRCAF L20

Created: 1943-08-14

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#11274>

PURPOSE OF FLIGHT:

Pupil practising low flying steep turns.

TECHNICAL OFFICER'S REPORT:

No evidence of failure to substantiate pilot's story.

NATURE OF ACCIDENT:

Turning to port inside engine cut momentarily causing A/C to spiral slightly. Instructor took control too late to avoid port motor striking small obstruction. Port engine loosened and propeller broken. Single engine forced landing successfully carried out, wheels down without further damage. Instructor contends inter-connecting cock "on".

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

1200/1007-1E

CLASSIFICATION:

~~18. Loss of control~~

19. Out of control

(19)

SECONDARY OR CONTRIBUTORY FACTORS:

~~24. Carelessness~~

ACTION TAKEN:

Log Book endorsed "Carelessness". Pilot logged.