

## CASPIR Aircraft Accident Cards

---

**Serial:** FE876

**Title:** North American Harvard Mk. IIB serial:FE876 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-September-09. Harvard IIB s/n FE876. This accident involved 2 people. Cole MA, Best R

**Keywords:** RAFHarvard IIB,FE876,34 SFTS,34 Service Flying Training School,Aerodrome,1943-September-09,Best,ColeRCAF L20

**Created:** 1943-09-09

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE876>



PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Dual flying practice.

Tail wheel tire burst after life of 81.45 hours.

NATURE OF ACCIDENT:

Tail wheel tire burst while taxiing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

15. Tire trouble.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil