

## CASPIR Aircraft Accident Cards

---

**Serial:** FE924

**Title:** North American Harvard Mk. IIB serial:FE924 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-September-10. Harvard IIB s/n FE924. This accident involved 2 people. Moreton AR, Odemark SC

**Keywords:** RAFHarvard IIB,FE924,34 SFTS,34 Service Flying Training School,Aerodrome,1943-September-10,Moreton,OdemarkRCAF L20

**Created:** 1943-09-10

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE924>



PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Formation Cross Country.

Nil

NATURE OF ACCIDENT:

Giving dual formation instruction when fuel pressure failed, so returned to base aerodrome using wobble pump Pupil carried out landing in a cross wind and grazed wing tip on landing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

*12/10/51*

CLASSIFICATION:

33 Technical defect.

SECONDARY OR CONTRIBUTORY FACTORS:

35. Cross wind & gusts

ACTION TAKEN:

Nil