

## CASPIR Aircraft Accident Cards

---

**Serial:** FE915

**Title:** North American Harvard Mk. IIB serial:FE915 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-September-13. Harvard IIB s/n FE915. This accident involved 2 people. Willmore PD, Landauer PM

**Keywords:** RAFHarvard IIB,FE915,34 SFTS,34 Service Flying Training School,Aerodrome,1943-September-13,Landauer,WillmoreRCAF L20

**Created:** 1943-09-13

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE915>



PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Night flying circuits and landings.

Nil

NATURE OF ACCIDENT:

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

Making dual landing at night. On lowering u/c, failed to put u/c lever into fully forward position, and u/c did not go fully down. Instructor failed to notice this and allowed pupil to complete the landing with the result that the u/c collapsed on landing.

FINDINGS:

SUMMARY No.

*LUC/PCD/W/I/UCDL ✓*

CLASSIFICATION:

~~31. U/C down but not fully locked.~~ 7  
*7. Others*

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

~~32. Pilot error.~~  
*32. W/C Drill In Air. 32*

Log book endorsed.