

(PURPOSE OF FLIGHT:	TECHNICAL OFFICER'S REPORT:) !
) Instrument flying.	Nil / -)
,) NATURE OF ACCIDENT:	12cg/POL/ON)
	Were authorized out for mutual in- strument flying practice. Intercom was serviceable and both pilots had previously been checked on instru- ment by Instructor. Unofficial re- ports from observers state the machin was low flying immediately prior to crash. A/C cut a considerable swath through the bush and disintegrated an burned. CLASSIFICATION:	further attempted a steep turn and mushed into the trees and crashed.	
	20 flew into Ground 20		
ſ	SECONDARY OR CONTRIBUTORY FACTORS:) .
	2 9	ACTION TAKEN: Nil))
	R. C. A. F. L 20 (REVISED) 7M-4-43 (3202) K. P. 5051 H. Q. 885-L 20	C. C. LTD. 7084-43)
))