

CASPIR Aircraft Accident Cards

Serial: 2569

Title: North American Harvard Mk.II serial:2569 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-September-29. Harvard II s/n 2569. This accident involved 2 people. Toothill E, Clark GC

Keywords: RAFHarvard II,2569,34 SFTS,34 Service Flying Training School,Aerodrome,1943-September-29,Clark,ToothillRCAF L20

Created: 1943-09-29

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2569>

PURPOSE OF FLIGHT:

Dual instruction.

NATURE OF ACCIDENT:

Tail wheel tire burst while taxiing.

TECHNICAL OFFICER'S REPORT:

Tail wheel tire burst after life of 76.50 hours.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

15. Tire failure.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil