

ACCIDENT CLASSIFICATION

UNIT 10 E.F.T.S Pendleton	COM. 3	PLACE Blanche Lake 14 miles N. of Buckingham, Que.	DATE 18-9-43	TIME 1145
A/C TYPE TIGER MOTH		NO. 5166	CRASH CAT. "A"	H.Q. FILE 1100-51-66
		S.E. x	M.E.	DAY x
				NIGHT

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Tingey, K.A.R.	F/S	R129466	FI	Uninj.	NO.	DATE
Warren, D.W.	LAC	R201093	PP	Uninj.	1263	18-9
					D 14 (REVISED)	
					NO.	CHECKED
					4	<input checked="" type="checkbox"/>
					#34	

ENGINE	ENGINE NUMBER (S)	SERIOUSLY	HOURS FLOWN BY PILOTS					
			INST.	NIGHT	ON TYPE		TOTAL	
Gypsy Major	2471/89314	Seriously			SOLO	DUAL	SOLO	DUAL
			49	68	638	20	841	141
			7	-	11	28	11	28

ACCIDENT CLASSIFICATION

COMMAND
MONTH
STAGE OF FLIGHT

- 7
- 4
- 2
- 1
- 7
- 4
- 2
- 1
- FORCED LANDING
- TAXYING
- LANDING
- TAKE-OFF
- FLIGHT
- STATRY
- FATAL
- INJ.
- 3RD
- 5
- 2

PURPOSE OF FLIGHT:

Seq. 11,14,17,18,& 21.

TECHNICAL OFFICER'S REPORT:

Nil
FS/HOP/ES/NA/NA/3

NATURE OF ACCIDENT:

Instructor claims engine failure in air and attempted to make forced landing in lake.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~54. Engine failure in the air.~~ 17
17 Forced Landing

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine trouble - Accident.
26

ACTION TAKEN:

Nil