

CASPIR Aircraft Accident Cards

Serial: FE337

Title: North American Harvard Mk. IIB serial:FE337 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-October-09. Harvard II s/n FE337. This accident involved 2 people. Moody R, Mayers C

Keywords: RAFHarvard II,FE337,41 SFTS,41 Service Flying Training School,R2
Ralph,1943-October-09,Mayers,MoodyRCAF L20

Created: 1943-10-09

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE337>

61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

ACCIDENT CLASSIFICATION

UNIT 41 S.F.T.S. Weyburn	COM. 2	PLACE R2 Ralph	DATE 9-10-43	TIME 1525
A/C TYPE HARVARD II		NO. FE337	CRASH CAT. "C"7	H.O. FILE 1300-FE337
		S.E. x	M.E.	DAY x
				NIGHT

COMMAND

MONTH

STAGE OF FLIGHT

7
4
2
1
7
4
2
1
FORCED LANDING
TAXYING
LANDING
TAKEOFF
FLIGHT
STATRY
FATAL
INJ. 3RD
INJ. 5
4

TYPE OF A/C
TYPE OF UNIT
CATEGORY

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Moody, R.	SGT	569925	FI	Uninj.	NO. A.183	DATE 10-10
Mayers, C.	SGT	618388	PP	Uninj.	D 14 (REVISED)	
					NO. 4	CHECKED <input checked="" type="checkbox"/>
					#37	

ENGINE	ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS					
			INST.	NIGHT	ON TYPE		TOTAL	
					SOLO	DUAL	SOLO	DUAL
Wasp AN-1R1340	11675/5369	Nil	32	70	540	90	615	117
			50	27	247	81	310	159

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Precautionary landing practice.

Nil

NATURE OF ACCIDENT:

A/C struck electrical installation within boundary of R2 immediately prior to precautionary landing carried out as demonstration.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

LCO/XOM ✓

CLASSIFICATION:

41. Hitting obstruction. 6

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN: