

## CASPIR Aircraft Accident Cards

---

**Serial:** AJ758

**Title:** North American Harvard Mk. II serial:AJ758 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-October-10. Harvard II s/n AJ758. This accident involved 2 people. Lepine-williams B, Moreton AR

**Keywords:** RAFHarvard II,AJ758,34 SFTS,34 Service Flying Training School,Aerodrome,1943-October-10,Lepine-williams,MoretonRCAF L20

**Created:** 1943-10-10

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ758>

ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.S. Medicine Hat	COM. 4	PLACE M.A.	DATE 10-10-43	TIME 1230
A/C TYPE HARVARD II		NO. AJ758	CRASH CAT. "D"1/72	H.Q. FILE 1300-AJ758
		S.E. x	M.E.	DAY x
				NIGHT

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING

TAXIING

LANDING

TAKE-OFF

FLIGHT

STATRY

FATAL

INJURY

3RD

5

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Moreton, A.R.	P/O	127830	FI	Uninj.	NO.	DATE
LePins-Williams, B	P/O	51063	PP	Uninj.	D 14 (REVISED)	
<p><i>1/14/43 FAILURE</i></p>					NO.	CHECKED
					22	<input checked="" type="checkbox"/>
					#57	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
Wasp S3HI	4328/8469 Nil	-	-	800	10	1300	100

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Dual instructions.

TECHNICAL OFFICER'S REPORT:

Tail wheel tire burst after life of 30.00 hours.

NATURE OF ACCIDENT:

Tail wheel tire burst while taxiing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

15. Tire Failure.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil