

CASPIR Aircraft Accident Cards

Serial: FE869

Title: North American Harvard Mk. IIB serial:FE869 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-October-31. Harvard IIB s/n FE869. This accident involved 2 people. Furness H, Hudson LA

Keywords: RAFHarvard IIB,FE869,34 SFTS,34 Service Flying Training School,Aerodrome,1943-October-31,Furness,HudsonRCAF L20

Created: 1943-10-31

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE869>

PURPOSE OF FLIGHT:

Precision landings.

TECHNICAL OFFICER'S REPORT:

Investigation.

NATURE OF ACCIDENT:

Pupil allowed a/c to swing after landing. Instructor took control but failed to prevent wing-tip striking the ground.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

33. Technical defect.

SECONDARY OR CONTRIBUTORY FACTORS:

61. Swinging on landing.

ACTION TAKEN:

Nil