


ACCIDENT CLASSIFICATION

UNIT 9 B.G.S. Monti Joli		COM. 3	PLACE 300 yds E of #1 runway, St. Flavis		DATE 7-10-43	TIME 1345			
A/C TYPE BATTLE		No. 2127	CRASH CAT. "B"	S.E. x	M.E.	DAY x	NIGHT		
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL		
Cadotte, J.L.		SGT	R136788	P	Uninj.		No. DATE		
Dawson, D.		LAC	R251971	AG/UT	Uninj.		N.66 8-10		
Andrews, H.R.		LAC	R256226	AG	Uninj.		D 14 (REVISED)		
							No. CHECKED		
							2		
							#4		
ENGINE		ENGINE NUMBER(S)		HOURS FLOWN BY PILOTS					
Merlin III		167757/25199 Slightly		DAY	NIGHT	ON TYPE		TOTAL	
						SOLO	DUAL	SOLO	DUAL
				37	40	28	3	128	125

COMMAND  
MONTH  
STAGE OF FLIGHT

FORCED LANDING  
TAXIING  
LANDING  
TAKE-OFF  
FLIGHT  
STATRY  
FATAL  
INJURY

ACCIDENT CLASSIFICATION



PURPOSE OF FLIGHT:

Scheduled gunnery exercise.

TECHNICAL OFFICER'S REPORT:

L/M/AOP/E/FT/4/L

NATURE OF ACCIDENT:

Nil

Engine failed due to glycol leak on final approach at 300'. A/C struck fence and ground and leaped into field short of runway.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

Further examination of the engine (Merlin III 25199/167757) in the subject aircraft disclosed a badly burnt flame trap at No.5 cylinder "A" bank.

CLASSIFICATION:

54. Engine failure in the air. 3

SECONDARY OR CONTRIBUTORY FACTORS:

38. Undershooting runway. 26

ACTION TAKEN:

Pending.