

PURPOSE OF FLIGHT: TECHNICAL OFFICER'S REPORT Dual instruction. Solo 17,22,25 NATURE OF ACCIDENT: Approached to land with a/c 10660 COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT: ) slightly beneath. Filot of 14436 FINDINGS: 2138 SUMMARY No. opened throttle, turned away. A/C 10660 CIRCUMSTANCES slipped into ground and turned over on Both a/c were approaching to land and were about its back. 200 ft. up. A.C.P. signalled Dual a/c with long red flashes from Aldis Lamp but they did not react promptly. After a few seconds solo a/c 19660 started to pull up and it looked as if its propellor hit the port elevator of a/c 14436 Both pilots stated they had not seen a red signal from the ground. CAUSE CLASSIFICATION: Mid air collision resulting from both pilots failing to maintain a careful lookout RECOMMENDATIONS COLLISIONS - A) #4 T.C. Instructions (Air Staff) A.11/16 be SECONDARY OR CONTRIBUTORY FACTORS: observed which provides for use of brown smoke puff when risk of collision between a/c exists. ACTION TAKEN: CONCLUSIONS OF A.I.B. Agree with findings. P/O Wesselius' failure to keep proper lookout was probably greater than LAC Alexander's. Need of improvement in ground R. C. A. F. L 20 (REVISED) 7M-4-43 (3202) K. P. 5051 organisation at this school. (Smoke puffs had not been issued to this school) H. Q. 885-L 20