

CASPIR Aircraft Accident Cards

Serial: FE810

Title: North American Harvard Mk. IIB serial:FE810 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-November-26. Harvard IIB s/n FE810. This accident involved 2 people. Hudson LA, Mellor GA

Keywords: RAFHarvard IIB,FE810,34 SFTS,34 Service Flying Training School,Aerodrome,1943-November-26,Hudson,MellorRCAF L20

Created: 1943-11-26

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE810>

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Local Dual

Tail wheel tyre burst after life of 168.40 Hours.

NATURE OF ACCIDENT:

Tail wheel tyre burst whilst taxiing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

TWC/07007

CLASSIFICATION:

43. Tire trouble.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL.