

	111111111111111
PURPOSE OF FLIGHT: TECHNIC	CAL OFFICER'S REPORT:
) Dual Instruction in Pilot Mavigation	
NATURE OF ACCIDENT:)
) A/C was seen to be diving steeply ancourt of recovering before final dive from FINDING	S: SUMMARY NO. 2175
which recovery was estimated to be attempted at about 1000 ft. A portion of	Filot apparently tried to recover at too low
) the a/c was seen to break away and the re- mainder of a/c dive steeply with a rotating motion. A/g struck ground at approx. angle of 70 to the horizontal.	an altitude and in so doing put excessive) strain on the mainplanes causing stbd. main-plane to come off.
Engine was heard to be running quite normally. Cloud base was high. Visibility good.	REMARKS OF C.I.Accidents Evidence suggests, althouthere is no proof that this accident was due to unauthorized
CLASSIFICATION: 28. Structural failure.	aerobatics. Pilot had been at school one) week and was in front cockpit. Structural
30 Mew into frounds	failure was caused by overstressing in recovery from a high speed dive.
SECONDARY OR CONTRIBUTORY FACTORS:	
16. Unauthorized low flying or ACTION TAKEN:	
39 Structural Failure N.A	•
17M-4-43 (3202) K. P. 5051 H. Q. 885-L 20	C. C. LTD. 7084-43