



PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Training - low flying; cross country.

Two small holes in upper and lower surface of stbd wing about two feet from centre section resulted.

NATURE OF ACCIDENT:

P/O Roberts, with P/O Davison under instruction, took off on low flying cross country exercise and proceeded to Flanagan Bay, turned south west to Silver Lake then east toward White Lake. At Spruce Hedge, out ten miles from White Lake, P/O Roberts noticed airspeed indicator unserviceable and returned to aerodrome.

The pressure line from the pitot to the A.S.I. was

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT: out.

FINDINGS:

SUMMARY No.

17/A/17

It is thought someone on the ground shot at the a/c when it was banked to the right. The bullet entered the upper surface of the main plane, cut the pressure line and continued through the lower surface of the main plane. Incident reported to R.C.M.P. through D.A.P.M.

CLASSIFICATION:

57. Miscellaneous.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil