

## CASPIR Aircraft Accident Cards

---

**Serial:** 3612

**Title:** Fleet Fort serial:3612 Accident Card

**Author:** Royal Canadian Air Force (RCAF)

**Subject:** This accident involved 1 aircraft on 1943-November-03. Fleet Fort 60K s/n 3612. This accident involved 2 people. Eiden HN, Paisley JK

**Keywords:** RCAFFleet Fort 60K,3612,3 WS,3 Wireless School,Stevenson Field  
Winnipeg,1943-November-03,Eiden,PaisleyRCAF L20

**Created:** 1943-11-03

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000741#3612>

ACCIDENT CLASSIFICATION

UNIT <b>3 W.S. Winnipeg</b>	COM. <b>2</b>	PLACE <b>Stevenson Airport</b>	DATE <b>3-11-43</b>	TIME <b>1315</b>
A/C TYPE <b>FORT 60K</b>	NO. <b>3612</b>	CRASH CAT. <b>"C"3</b>	H.Q. FILE <b>1100-36-12</b>	
		S.E. <b>X</b>	M.E.	DAY <b>X</b>
				NIGHT

COMMAND

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
<b>Faisley, J.K.</b>	<b>SGT</b>	<b>R181023</b>	<b>F</b>	<b>Uninj.</b>	NO. <b>4-58</b>	DATE <b>4-11</b>
<b>Eiden, H.M.</b>	<b>LAC</b>	<b>R218137</b>	<b>WO</b>	<b>Uninj.</b>		
					D 14 (REVISED)	
					NO. <b>2</b>	CHECKED <input checked="" type="checkbox"/>
					<b>#1</b>	

MONTH

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS			
		INST.	NIGHT	ON TYPE	
<b>JACOBS LOMB</b>	<b>15777/1962</b>	<b>H11</b>			
				SOLO	DUAL
				SOLO	DUAL
				TOTAL	
				SOLO	DUAL

STAGE OF FLIGHT

ACCIDENT CLASSIFICATION

- FORCED LANDING ( )
- TAXIING ( )
- LANDING ( )
- TAKE-OFF ( )
- FLIGHT ( )
- STATRY ( )
- FATAL ( )
- INJ. ( )
- 3RD ( )
- 5 ( )
- M 2 ( )

TYPE OF A/C  
TYPE OF UNIT  
CATEGORY

61  
60  
59  
58  
57  
56  
55  
54  
53  
52  
51  
50  
49  
48  
47  
46  
45  
44  
43  
42  
41  
40  
39  
38  
37  
36  
35  
34  
33  
32  
31

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
RAI  
M 2

PURPOSE OF FLIGHT:

Wireless exercise.

TECHNICAL OFFICER'S REPORT:

Nil

*19/12/55*

NATURE OF ACCIDENT:

Shortly after landing, a/c started to swerve to port, pilot started to apply opposite rudder and throttle, and pilot's foot slipped off rudder. The swerve developed into a ground loop, and stbd oleo leg collapsed.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~01. Swinging on landing.~~

*2. Swung*

*2*

SECONDARY OR CONTRIBUTORY FACTORS:

~~24. Carelessness.~~

ACTION TAKEN:

Log book endorsed "Carelessness".