

PURPOSE OF FLIGHT: TECHNICAL OFFICER'S REPORT: Local circuits precautionary 100/A00/18F/A/I/WVC W landings. NATURE OF ACCIDENT: Pupil was authorized for precautionary COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT: landings and local circuits. He was FINDINGS: SUMMARY No. 2189 warned about weather although at the Cause time of take off weather was good. Pilot unable to maintain control during sudden snow ) Snow was so thick, he was unable to squall allowing a/c to dive into ground. get into main aerodrome from the R2 Recommendations and appears to have spun into the Strict supervision of pilots u/t. in weather fore-) ground. No witnesses available and cast briefing. More rigid discrimination be used a/c missing some three hours washing in or out border line or under average studbefore being found. ents. Conclusions of A.I.B. Agree with findings. CLASSIFICATION: Note: Proceedings contain no explanation why pupil sent off when expected snow squall was at the time 30 mins.past due. Investigating Officer commented upon failure to cease training this pilot. Sequence numbering at this Unit not in accordance INABILITY TO MAINTAIN FOULLIBRIUM. ACTION TAKEN: with C.A.P. 1 Vol.II, second Edit. Nil. R. C. A. F. L 20 (REVISED) 7M-4-43 (3202) K. P. 5051 H. O. 885-L 20