

## CASPIR Aircraft Accident Cards

---

**Serial:** FP905

**Title:** Avro Anson Mk. II serial:FP905 Accident Card

**Author:** Royal Canadian Air Force (RCAF)

**Subject:** This accident involved 1 aircraft on 1944-January-20. Anson II s/n FP905. This accident involved 2 people. Giguere JAR, Hennan J

**Keywords:** RCAFAnson II,FP905,12 SFTS,12 Service Flying Training School,Aerodrome,1944-January-20,Giguere,HennanRCAF L20

**Created:** 1944-01-20

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#FP905>



PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Dual S.B.A.

Nil

NATURE OF ACCIDENT:

700/10000/0003

Pupil pilot attempted to start both engines of a/c unsuccessfully. ACI Giguere entered cockpit of a/c, started stbd engine then port engine and port oleo leg immediately collapsed. Neither the student or ground crew did a complete cockpit check as the u/c selector was subsequently found in the "up" position.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

8

~~57. Miscellaneous.~~

8. u/c failure

SECONDARY OR CONTRIBUTORY FACTORS:

~~5. U/C drill on take off.~~

52. u/c drill on ground.

35

ACTION TAKEN:

Instructor logged. Log book endorsed Gross Carelessness and "Faulty cockpit drill".