

ACCIDENT CLASSIFICATION

UNIT 32 O.T.U.		COM. WAC	PLACE M.A.		DATE 6-1-44	TIME 1545		
A/C TYPE DAKOTA III		NO. 558	CRASH CAT. PROP		H.Q. FILE 1300-FZ558			
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL	
VINCENT, W.		CPL	570554	Fitt II	Uninj.		NO. DATE	
BACON, G.W.		LAC	1010972	Fitt II	Slightly Inj.		A284 8-1-44	
							D 14 (REVISED)	
							NO. CHECKED	
							#1	
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS				
Twin Wasp.		P. CP350094 S. CP350096		INST.	NIGHT	ON TYPE		TOTAL
						SOLO	DUAL	SOLO DUAL
				-	-	-	-	- -

COMMAND
MONTH
STAGE OF FLIGHT

- 7
- 4
- 2
- 1
- 7
- 4
- 2
- 1
- 1
- FORCED LANDING
- 1
- TAXYING
- 1
- LANDING
- 1
- TAKE-OFF
- 1
- FLIGHT
- 1
- STATRY
- 1
- FATAL
- 1
- INJ.
- 3RD
- 1
- INJURY
- 5
- 1
- RAF
- M 2

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Instruction in Starting Procedure. NI L.

TECHNICAL OFFICER'S REPORT:

NATURE OF ACCIDENT:

GB. 1010972 LAC. Bacon G.W. Fitt. 11E
was struck by the port propellor during
instruction being given by N.C.O. to
another airman in cockpit of a/c.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

56. Propellor swinging.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN: