

CASPIR Aircraft Accident Cards

Serial: HB135

Title: Beechcraft Expeditor Mk. IMN / 3T serial:HB135 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 2 aircraft on 1944-February-19. They are: Beechcraft UC45B s/n HB105, Beechcraft UC45B s/n HB135. This accident involved 2 people. Raffan JT, Webb DJ

Keywords: RAFBeechcraft UC45B,HB135,32 OTU,32 Operational Training Unit,Boundary Bay British Columbia Aerodrome British Columbia,1944-February-19,Raffan,WebbRCAF L20

Created: 1944-02-19

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000565#HB135>

61 () 60 () 59 () 58 () 57 () 56 () 55 () 54 () 53 () 52 () 51 () 50 () 49 () 48 () 47 () 46 () 45 () 44 () 43 () 42 () 41 () 40 () 39 () 38 () 37 () 36 () 35 () 34 () 33 () 32 () 31 ()

ACCIDENT CLASSIFICATION

UNIT 32 O.T.U. Pat. Bay.		COM. WAC	PLACE Boundary Bay Aerodrome, B.C.		DATE 19-2-44	TIME 2020	
A/C TYPE BEECHCRAFT UC45B		NO. HB.105 HB. 135-D	CRASH CAT. "D" "E"		H.Q. FILE 1300-UB105	S.E. M.E. DAY NIGHT	
PERSONNEL		RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Webb, D.J.		F/O	141479	P	Uninj.	NO. DATE	
Raffan, J.T.		F/L	90938	P	Uninj.		
						D 14 (REVISED)	
						NO. CHECKED	
						#2 ^R / 2 / 2	
ENGINE Wasp Junior		ENGINE NUMBER (S) P. AC/42/23346 S. AC/42/23547 P. AC/42/122318 S. AC/42/122482		HOURS FLOWN BY PILOTS			
		INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
		60	56	24	3	546	170
		36	63	18	5	1124	160

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

7
4
2
1
7
4
2
1
Forced Landing
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ. 3RD
INJ. 5

ACCIDENT CLASSIFICATION

1 () 2 () 3 () 4 () 5 () 6 () 7 () 8 () 9 () 10 () 11 () 12 () 13 () 14 () 15 () 16 () 17 () 18 () 19 () 20 () 21 () 22 () 23 () 24 () 25 () 26 () 27 () 28 () 29 () 30 () 31 () 32 () 33 () 34 () 35 () 36 () 37 () 38 () 39 () 40 () 41 () 42 () 43 () 44 () 45 () 46 () 47 () 48 () 49 () 50 () 51 () 52 () 53 () 54 () 55 () 56 () 57 () 58 () 59 () 60 () 61 ()

PURPOSE OF FLIGHT:

Night Circuits

TECHNICAL OFFICER'S REPORT:

NIL

TCA / PCL

MULT ✓

NATURE OF ACCIDENT:

Beechcraft HB. 105 was parked near end of Runway waiting for permission to taxi on to Runway and take off, when Beechcraft HB. 135 taxied up behind and collided.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~3. Hitting other Aircraft.~~

9. collisions

9

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL