

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62
ACCIDENT CLASSIFICATION																																																													
UNIT 8 S.F.T.S. Weyburn, Asak.		COM. 2	PLACE R.I Aerodrome Halbrite, Sask.		DATE 6-3-44	TIME 0930	H.Q. FILE		COMMAND																																																				
A/C TYPE HARVARD IIB			NO. Fe442	CRASH CAT. "D" 3	S.E. x	M.E.	DAY x	NIGHT	MONTH																																																				
PERSONNEL			RANK	NUMBER	DUTY	INJURIES		SIGNAL		STAGE OF FLIGHT																																																			
Heine, W.C.			P/O	J37141	F.I.	Uninj.		NO.	DATE	FORCED LANDING																																																			
Smith, R.F.D.			LAC	R211400	LAC	Uninj.		D 14 (REVISED)		TAXIING																																																			
								NO.	CHECKED	LANDING																																																			
								#9		TAKE-OFF																																																			
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS				TOTAL		FLIGHT																																																			
WaspR1340-AN1		42-9774/22113		Slight				391		STATRY																																																			
				DAY	NIGHT	ON TYPE		TOTAL		FATAL																																																			
						SOLO	DUAL	SOLO	DUAL	INJ.																																																			
				44	29	201	102	236	155	BRD																																																			
				28	15	50	67	83	03	M																																																			
ACCIDENT CLASSIFICATION																																																													
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62

PURPOSE OF FLIGHT:

Armament Training.

TECHNICAL OFFICER'S REPORT:

NIL

NATURE OF ACCIDENT:

Taxying accident. While parking, a/c struck a steel fence post, also stbd. mainplane hit small building causing damage to the aircraft.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

730/1927 ✓

CLASSIFICATION:

9

2. Hitting obstructions.

SECONDARY OR CONTRIBUTORY FACTORS:

24. Carelessness.

ACTION TAKEN:

Pilot placed on charge.