

))))))))))))))))	·))))))
PURPOSE OF FLIGHT:	TECHNI	CAL OFF	ICER'S RE	EPORT:	Lucles	DUF/U	€ }		
Ferrying.		NI	L		*	r)
NATURE OF ACCIDENT:)
Wheels up landing. On downwind appr	roa-COURT	OF INQU	RY OR IN	IVESTIG	ATING OI	FFICER	'S REP	ORT:)
) ch pilot throttled back slightly to	FINDING				SUMMAR		_	_)
lose extra height and the u/c warning commenced blowing. Pushed the cut-c)
and proceeded with mircuit. Pilot o	checked)
switches, fuel and mixture controls closed the throttles. Horn did not)
likely to the fact that pilot had no	prow ane)
oup throttles sufficiently to re-set	horn on)
a/c. Pilot did not sheck mechanical devices. Completed cross-wind leg ar	Warning	had)
CLASSIFICATION: final approach, lowe	ring flap)
) preparatory to landi	.ng.)
) 34. W heels up landing .)
SECONDARY OR CONTRIBUTORY FACTORS:)
%. Pflot error.	ACTION	TAKEN)
32 left Dull- h'a	<u> ۸۵٬۱۵۱۲</u>	TATALLA.)
) 24 Carelessness. R.C.A.F. L 20 (Revised)	- ,	Log bool	k endors	ed.)
) 7M.4-43 (3202) K.P. 5051 H. Q. 885-L 20							C. C. LTD.	. 7084-4	з)
[· · · · · · · · · · · · · · · · · · ·))))))))))))))))))))