

TECHNICAL OFFICER'S REPORT: TLOS A MENTE /en PURPOSE OF FLIGHT: Circuits and landings. NATURE OF ACCIDENT: COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT: A/C carrying out night circuits SUMMARY No. 2377) turned right shortly after take-FINDINGS: off and crash d about a mile NE of CAUSE: Inability to maintain equilibrium. serodrome and burned out. Pilot was Possibility that pilot may not have fully uncaged) killed. his instruments cannot be overlooked. RECOMMENDATIONS: Nil CONCLUSIONS OF A.I.B. This accident probably caused by the inability of a u/t pilot to maintain equilibria. on instruments on a night take-off. (a) The evidence disclosed that it is possible that this pilot might not have fully uncaged his gyro instruments (b) The evidence further discloses that it is CLASSIFICATION: very doubtful whether this pilot was sufficiently advanced in his training to solo at might at all and particularly so under conditions as they existed at the time of the accident. SECONDARY OR CONTRIBUTORY FACTORS: **ACTION TAKEN:** Piket climbed To 1000 ASSECN BY ACO MIT. R. C. A. F. L 20 (REVISED) C. C. LTD. 7084-43