

	· · · · · · · · · · · · · · · · · · ·	)	) )	) ) )	)	) )	<b>5</b> 5	) ) ]	)	) ) )	))
ĺ	PURPOSE OF FLIGHT:	TEC	CHNICA	L OFFIC	ER'S	REPOR	<u> </u>				•
	Seq. 26 (12&13)	Ni:	1.		L	5/1					)
ı	NATURE OF ACCIDENT:					1					)
	A/C bounced on landing and was then	COL	URT OF	INQUIR	Y O	R INVES	TIGATIN	G OFFI	CER'S	REPORT	) :
	) let down with throttle on three point	tFIN	IDINGS	Ė			SUM	MARY I	<u> 10.</u>		)
1	) Left wing dropped and although left										5
	rudder was applied the a/c ground looviolently to the right. Visibility										)
	excellent although there was no moon										-
	)										
	)							•			)
	)										)
	)										)
	CLASSIFICATION:										)
	38. Ground loop.							•			)
	4 Heavy										)
i	SECONDARY OR CONTRIBUTORY FACTORS:										)
		AC.	TION T	AKEN:							)
	)			pilot'.	s lo	og book	endor	sed an	d log	ged for	. ,
1	R, C, A, F, L, 20 (REVISED) 7M-4-43 (3202) K, P, 5051 H, O, 885-1, 20								c.	C.LTD. 708	34.43
	) ) ) ) ) ) ) ) ) ) ) ) ) ) ) ) ) ) )	)	) )	) ) )	)	) )	) )	) ) ,	) ) .	) ) )	