

CASPIR Aircraft Accident Cards

Serial: HB135

Title: Beechcraft Expeditor Mk. IMN / 3T serial:HB135 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-June-09. Beechcraft Expeditor I s/n HB135.
This accident involved 2 people. Barton AD, Koror R

Keywords: RCAF Beechcraft Expeditor I, HB135, 6 OTU, 6 Operational Training Unit, Aerodrome, 1944-June-09, Barton, Koror RCAF L20

Created: 1944-06-09

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000565#HB135>

PURPOSE OF FLIGHT:

Circuits and landings.

NATURE OF ACCIDENT:

A/C touched down with second pilot at controls when there was a scraping sound. Instructor took over, completed another circuit, lowered landing gear by emergency method, and landed a/c without further incident.

CLASSIFICATION:

5. U/C failure.

SECONDARY OR CONTRIBUTORY FACTORS:

35. U/C defect.

TECHNICAL OFFICER'S REPORT:

LUC/UDW

A/C battery was found to be low, though it was O.K. prior to flight. This condition of battery would account for temporary failure of electrical portion of u/c lowering system

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

LUC/UDW ✓

ACTION TAKEN:

NIL