

ACCIDENT CLASSIFICATION

UNIT 9 B.G.S. Mont Joli		COM. 3	PLACE 8 miles SW of M.A.		DATE 28-6-44	TIME 0758	
A/C TYPE BATTLE		NO. 7435		CRASH CAT. "C"	S.E. X	M.E.	DAY X
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL
REGIMBAL, J.P.		SGT	R200066	P	Uninj.		NO. N.91
DOLLARD, V.P.		LAC	R292586	AG	Uninj.		DATE 28-6
KENT, G.J.		LAC	R280655	AG	Uninj.		D 14 (REVISED)
							NO. 2
							CHECKED
							#2
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS			
Merlin III		31871/8589 slight		INST.	NIGHT	ON TYPE	
						TOTAL	
				SOLO	DUAL	SOLO	DUAL
				31	15	49	5
						134	139

ACCIDENT CLASSIFICATION

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STAT'RY
FATAL
INJ.
INJURY 3rd
M/Z

PURPOSE OF FLIGHT:

Scheduled camera gun exercise.

NATURE OF ACCIDENT:

Engine failure in the air, internal glycol leak in A BANK.

TECHNICAL OFFICER'S REPORT:

Examination disclosed an internal glycol leak "A" Bank.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

17. Forced landing.

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine Trouble - accident.

ACTION TAKEN:

NIL