

PURPOSE OF FLIGHT:

Practice Flight Seq. 9,10,12,15,17,21 Mil.

22 S.E. Landing.

NATURE OF ACCIDENT:

Student Pilot in a/c 7823 was practicing forced landings; at approx. 150 ft. when the throttles were opened the port engine failed to respond, the Pilot was unable to maintain height on one engine and so he carried out a wheels up landing straight ahead.

TECHNICAL OFFICER'S REPORT:

ILFM/AOP/ES/NK/IL
ILFM/AOP/PSFILE/ES/NK/IL/UOK/B
COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:
FINDINGS: SUMMARY No.

CLASSIFICATION:

17. Forced Landing.

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine trouble - Accident.

ACTION TAKEN:

Investig.