

ACCIDENT CLASSIFICATION

UNIT 1 A.O.S. Malton	COM. 1	PLACE Markham Township	DATE 7-8-44	TIME 0930				
	H.Q. FILE 1700-1729							
A/C TYPE ANSON IV	NO. W1729	CRASH CAT. "A"	S.E. X	M.E. X	DAY X	NIGHT		
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL	
McHardy, M.		SGT	R86572	P	Killed		NO. M674	DATE 7-8
Bruce, W.I.		SGT	R186736	2P	Killed		D 14 (REVISED)	
							NO.	CHECKED
							#3	
ENGINE	ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS					
Wright Whirl Wind	18607/43060		INST.	NIGHT	ON TYPE		TOTAL	
	18740/43264				DUAL	SOLO	DUAL	SOLO
			51	105	112	373	174	406
			48	82	112	350	155	395

COMMAND
MONTH
STAGE OF FLIGHT

7
4
2
1
7
4
2
1
FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ
3RD
INJURY
5
N

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Pilot Practice.

TECHNICAL OFFICER'S REPORT:

IM/PTW/ES/PM/PHI

NATURE OF ACCIDENT:

Structural failure in the air, Under investigation, accident Investigation board.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No. 2425

CAUSE: Structural Failure.

RECOMMENDATIONS: Nil.

CONCLUSIONS OF A.I.B.: See Summary No. 2425.

CLASSIFICATION:

18. Misc. Technical.

SECONDARY OR CONTRIBUTORY FACTORS:

39. Structural Failure.

ACTION TAKEN: