

/)}}};	9 -
PURPOSE OF FLIGHT: TECHNICAL OFFICER'S REPORT:	•
) Transportation	)
NATURE OF ACCIDENT: LS PSS PSJ USS WWC	)
After overshooting twice on attemptingourt of INQUIRY OR INVESTIGATING OFFICER'S REPORT:	)
to land on N/S runway at Toronto I. FINDINGS: SUMMARY No.	`
airport the runways were changed by C.O.	,
and pilot approached to land into west on	)
E/W runway. Wheel landing was made, and	)
after two bounces, a/c settled down onto	<b>3</b>
three points. Swing to left into wind	
developed and pilot applied right brake	
this failed to stop swing and brakes were then pumped to bring up pressure and left	3
engine was opened up. ground loop was well	3
) cdessinged byc collapsed a/c coming to rest	
On runway.	7
	)
) 2. Swung.	
	•
SECONDARY OR CONTRIBUTORY FACTORS:	
ACTION TAKEN:	)
<del></del>	)
Pilots log Book Endorsed.	)
R. C. A. F. L 20 (REVISED) 2M-5-44 (4638) K.P. 8689	•
C. C. LTD. 20157-44	<i>3</i> .
	J