

ACCIDENT CLASSIFICATION

UNIT 9 B.G.S. Mont Joli	COM. 3	PLACE 6 miles E of M.A.	DATE 15-8-44	TIME 1625
A/C TYPE BATTLE	NO. 1662	CRASH CAT. "C"	H.Q. FILE 1100-16-62	
			S.E. X	M.E.
			DAY X	NIGHT

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
BAYTOR, K.J.	F/S	R148381	P	Uninj.	NO.	DATE
REST, C.R.	LAC	R272546	DC	Uninj.	N101	15-8
					D 14 (REVISED)	
					NO.	CHECKED
					4	<input checked="" type="checkbox"/>
					#4	

ENGINE	ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS					
			INST.	NIGHT	ON TYPE		TOTAL	
Merlin III	8623/8067	slight			DUAL	SOLO	DUAL	SOLO
			34	23	2	20	103	675

ACCIDENT CLASSIFICATION

COMMAND

MONTH


STAGE OF FLIGHT

- FORCED LANDING
- TAXYING
- LANDING
- TAKE-OFF
- FLIGHT
- STATRY
- FATAL
- INJ.
- 3RD
- 5
- 4
- 3
- 2
- 1
- 7
- 1
- 2
- 4
- 7
- 1
- 2
- 4
- 7

TYPE OF A/C

TYPE OF UNIT

CATEGORY



PURPOSE OF FLIGHT:

Scheduled target towing for gunnery exercise.

NATURE OF ACCIDENT:

Engine failure in air due to internal glycol leak. Pilot forced landed with wheels retracted.

TECHNICAL OFFICER'S REPORT:

Internal glycol leak "B" bank.

FB/AOP/ES/GL/D/I/UOK/B

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

17. Forced landing.

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine trouble - accident.

ACTION TAKEN:

NIL