

61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

ACCIDENT CLASSIFICATION

UNIT 9 B.G.S. MonteJoli	COM. 3	PLACE Sta Luce,	DATE 21-8-44	TIME 1320
A/C TYPE BATTLE		NO. 1698	CRASH CAT. "B"	H.Q. FILE 1100-16-98
		S.E. X	M.E.	DAY X
				NIGHT

COMMAND

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
TAYLOR, J.W.	P/O	06703	F	Uninj.	NO.	DATE
DUBOIS, J.A.	CPL	R125463	DC	Uninj.	1103	21-8
					D 14 (REVISED)	
					NO.	CHECKED
					6	<input checked="" type="checkbox"/>
					#5	

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STABILITY
FATAL
INJ.
3RD
INJURY

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS						
		INST.	NIGHT	ON TYPE		TOTAL		
				DUAL	SOLO	DUAL	SOLO	
Merlin III	119623/8523	weight	42	19	7	324	123	666

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 RAF

PURPOSE OF FLIGHT:

Scheduled target towing.

NATURE OF ACCIDENT:

Engine failure on return to aerodrome from drogue lines. Loud bang in engine and then it cut out. Pilot changed to fine pitch but without effect. He forced landed wheels up in grass field having shut off switches and gas.

TECHNICAL OFFICER'S REPORT:

Further investigation

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

LB/AOP/PCDUW/ES/NK/1/UCDE

SUMMARY No.

CLASSIFICATION:

- 17. Engine
- 17. Forced landing.

SECONDARY OR CONTRIBUTORY FACTORS:

- 26. Engine trouble - no damage.

ACTION TAKEN:

NIL