

PURPOSE OF FLIGHT: TECHNICAL OFFICER'S REPORT: Routine mavigation exercise. NATURE OF ACCIDENT: Ragine failure (port COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT: Gradual less of oil pressure everturi! engine failure. FINDINGS: SUMMARY No. Oil pressure failed to Port engine: CAUSE: Lubrication trouble in the port motor. prop going into full fine pitch; prior Fault shown on minor u/s report page of L.14 to complete less of oil pressure, oil might have had some bearing on the matter. pressure gauge was functuating somehwat: RECOMMENDATIONS: That crews become more familia pilot noticing this throttled back port with the equipment in the a/w so that all surp engine to 20" boost and at 32" beest in equip. may be jettisoned in emergency thus stbd. engine climbed to 3500' where lightening the load. eventually port engine started vibrating CONCLUSIONS OF A.I.B. badly: P cut engine soon after prop Agree with findings. CLASSIFICATION: seized. Remarks of C.O. I do not consider the evidence sufficient to 17. Forced landing on sea. warrant the laying of charges against any person involved. SECONDARY OR CONTRIBUTORY FACTORS: Engine trouble - accident. **ACTION TAKEN:** NIL R. C. A. F. L 20 (REVISED) M-5-44 (4638) K. P. RERA