

PURPOSE OF FLIGHT: TECHNICAL OFFICER'S REPORT: Ferrying a/c from a/c repair LTD., Edmonton. ILOC ADCI NATURE OF ACCIDENT: A/C apprenched scene of accident COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT: flying at an eltitude of 1900ft. FINDINGS: SUMMARY No. It was observed by several witnesses CAUSE: Loss of control. Contributary factorsand the substance of their evidence Occupants not strapped in and possibility that was that the a/c was seen first control cables might have been fouled by sutton rocking from side to side after which or parachute harness dropping down". it fell into a right hand spin in RECOMMENDATIONS: which it continued until it crashed. CONCLUSIONS OF A.I.B. Less of control due to some obscure reason. Morre. 1. The 1.0. found breaches of C.A.P.100, Sec. 11, para, 2 and Section 15, para which respectively provide for the wearing of CLASSIFICATION: perachute and fustening of safety belts. MOTE: 2 The passenger, LAC Dixon, had flown from 19. Out of control. Calgary to Edmonton as crosses in an Anson. He 3 apparently elected to return with F/O Andrew in Harvard but there is no record of his flight being SECONDARY OR CONTRIBUTORY FACTORS: authorized and the flight plan filed by F/O Andrew **ACTION TAKEN:** did not show the name of LAC Dixon as a passenger in a/c. NIL R. C. A. F. L 20 (REVISED)