



PURPOSE OF FLIGHT:

Night circuits.

NATURE OF ACCIDENT:

Pupil pilot making night approach undershot flare path and struck aerodrome boundary fence damaging u/c. A/C stayed airborne and a 3 point landing was made. A ground loop resulted from the damaged u/c.

CLASSIFICATION:

3. Undershot.

SECONDARY OR CONTRIBUTORY FACTORS:

TECHNICAL OFFICER'S REPORT:

NIL

LU/PSU

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

ACTION TAKEN:

NIL